Environmental Site Remediation Database Search Details 416 Waverly Avenue, Mamaroneck, New York

Spill/Remediation Number	Address of Property	Site Name	Site Description Notes	Site Environmental Assessment	Site Health Assessment	Location of Property from 416 Waver
•	,			, socosmen	Site Health Assessment	Ave/560 Fenimore Rd
				l '		
				•	, ·	
			,			
			·			
•			Consists of 4 parcels			
			Parcel 1: 8-829-69 Parcel 2: 8-829-92		i	
			Parcel 3: 8-829-41	Remediation is complete.		
•			Parcel 4: 8-829-51	•		
			Site boundaries modified to include Parcel 1 & 4 due to disposal history & current groundwater impacts.	Prior to remediation, the primary contaminants of		1
			Parcel 2 & 3 have been excised from site as no disposal occured on these parcels and not affected by Freon-113.	concern were Freon 113 and	Contact with contaminated soil is not	
	605 Center Avenue and		Current site size is 0.34 acres; consists of two story building & two parking areas.	its breakdown products.	expected because site is covered by	
	604 Fayette Avenue (vacant parking lot and was			Remaining contamination in	buildings and pavernent.	
	used for waste storage and		M-1 (manufacturing) zone in industrial/commercal/residential area.	groundwater is being	Drinking contaminated groundwater is not	605 Center Ave - approx. 1,059.11 ft
360025	is likely area of disposal)	Former EMCA Site	Past Use: subsidiary of Rohm & Haas, owned and operated the site to manufacture electronic conducting paste.	managed under a Site Management Plan,	likely since area is supplied with public water.	604 Fayette Ave - approx 1,075.56 ft
			•			
						•
			Off-site component of the Former Argueso and Co., Inc site [C360108] located on 441, 442, 501 and 513 Waverly			
	·		Ave.			
			Site is immediate surrounding properties located in urban area adjacent to main site.		,	· ·
			On-site properties are located on opposite sides of Waverly Avenue – site features were two buildings and two parking areas.			
			Building at 442 was demolished in 2010 – off site component comprised of immediately surrounding properties,		·	
			Surrounding properties are zoned for commerical use.	On site area [C360108] -		
	,		Properties are used for parking lots, commercial establishments, and a residential lot.	primary contaminants include pretroleum, volatile organic	Info submitted with BCP application re:	
C360108A	441-442 Waverly Avenue	Former M. Argueso and Co., Inc-Off-Site		compounds and semivolatile	the conditions at site are currently under review and will be revised as additional	441 Waverly Ave - approx, 406,54 ft
0000100A	TTI TTE Wavelly Aveilde	and Co., inc-On-Site	Past Use; was used for wax refining and manufacturing.	organic compounds	info becomes available.	442 Waverly Ave - approx. 432.12 ft
	,					
			·		·	
					[
			9			
			,		Contact with contaminated soil is unlikely	
					as the site is covered by buildings and pavement	
					Contaminated groundwater at the site is	
					not used for drinking or other purposes and area is served by public water supply	
				1	that obtains water from a different source	
			,		not affected by this contamination sampling indicates that elevated	
			Located in urban area at 441, 442, 501 & 513 Waverly Avenue		concentrations of site-related	
	444 440 704 0 546		1.0359 acres in size		contaminants in groundwater at the site perimeter are present; therefore soil vapor	REFER TO ABOVE FOR 441 & 442
C360108	441, 442, 501 & 513 Waverly Avenue	Former M. Argueso and Co., Inc-Off-Site	zoned for commercial uses 3 out 4 of the properties rented to telecommunications cable. The 4th properties rented to telecommunications cable.	Contain same contaminants	intrusion may be a concern for off-site	Waverly Ave 501 Waverly Ave - approx. 456.80 ft
**************************************		,o on one	3 out 4 of the properties rented to telecommunications cable. The 4th property is used as a parking lot	as stated above	buildings.	513 Waverly Ave - approx. 510.90 ft

Spill/Remediation	* 11. * * * * * * * * * * * * * * * * *			Site Environmental		Location of Property from 416 Waverly
<u>Number</u>	Address of Property	Site Name	Site Description Notes	<u>Assessment</u>	Site Health Assessment	Ave/560 Fenimore Rd
				1		
			•			
			. , , ,			·
		*				
'				1	•	
						·
		1		Soils & groundwater at site	·	
		į.	Located in an industrial area on comer of Fenimore Ave & Center Street	have been contaminated with		'
		į	Single story metal and masonry block building which covers most of the site.	volatile organic compounds	,	
	.}		<u>l</u>	and metals.	Ì	/
			Was previously an automotive repair shop – property was foreclosed upon.	Environmental assessment	·	
	·		Tank removal and environmental assessment was performed at site which revealed contaminated groundwater -		As info becomes available, it will be	
			not clear whether the contamination is site related.	groundwater in monitoring	reviewed by the NYSDOH to determine if	
		l		wells and contaminated soluis		·
С	624 Fenimore Avenue	624 Fenimore Avenue	Past Use; was used for wax refining and manufacturing.	in unlined pits inside facility.	exposure concerns.	Approx 395.76 ft
			,			
					· ·	
		į	, ,		Contaminated soils remain at site below	
				i e	concrete or clean backfill, people will not	
			· ·		come in contact with contaminated soil unless they dig below the surface	
			,		materials.	· ·
		•		1	materials.	1
1		İ		1	Contaminated groundwater at the site is	· ·
					not used for drinking or other purposes	
į.	İ		·		and area is served by public water supply	
	,				that obtains water from a different source	
			Located in urban area and is .92 acres - single story building approx 20,000 sq. ft. which sits on a concrete slab.	1	not affected by this contamination.	
	1	ł	Rest of property consists of asphalt parking lot & landscapred area.		Volatile organic compounds in	
		1 .	Trees of Property serious of aspirate batterial for a tantasousprou arous	1	groundwater may move into soil vapor	1
		ł	Current zoning and land use: currently a retail stotre and it's M-1 and allows certain commercial and industrial	1	and may affect indoor air quality.	
1			applications.	1		,
	1	1		L	Soil vapor intrusion sampling identified	,
		1	Surrounding parcels are used for residential, commercial and industrial purposes.	Prior to remediation, primary contaminants are concerns of	impacts in indoor air quality – this impact is limited to one on-site building and	
360027	139 Hovt Street	ITT Sealectro	Past Use: manufactured electronic parts and jewelry at site.	volatile organic compounds:	represents a health concern.	Approx 1,232.62
500021	1 100 1 10 yr Ollegi	1 11 Cealectio	It as cost trianglactured electronic parts and joinerly at site.	I voidure organic compounds:	hebicoomo a neami concem.	TUPPION ILEGEIOE

Spill Incidents Database Search Details

			opin moldents batabase ocaren betans		
Spill Number	Spill Date	Spill Time	Location of Spill & Name	Date Spilled Closed	<u>Details</u>
			416 Waverly Avenue		
. 304697	8/2/2003	3:30PM	Murphy Brothers Contracting	3/29/2004	Tank Test Failure
			416 Waverly Avenue		
304698	8/1/2003	4:30PM	Murphy Brothers Contracting	3/29/2004	Tank Test Failure